

# Large Maint, Kit.

1. Absence of Allen wrench for handle of needle valve.
2. Absence of "Lift-the-dot" fasteners.